

SITE: NL/Dutch Boy Paints Site
LOCATION: Perth Amboy, New Jersey
DESCRIPTION: OHM sampling drums in
bldg #4
DATE: 5/10/93

354621







SITE: NL/Dutch Boy Paints Site
LOCATION: Perth Amboy, New Jersey
DESCRIPTION: OHM transferring oil
into DOT shippable containers
DATE: 5/12/93



5 12 93

SITE: NL/Dutch Boy Paints Site

LOCATION: Perth Amboy, New Jersey

**DESCRIPTION: Bldg #3 in North area
by transformers 6,7,&8**

DATE: 5/12/93

5:293



SITE: NL/Dutch Boy Paints Site

LOCATION: Perth Amboy, New Jersey

**DESCRIPTION: OHM cleaning up PCB
debris in bldg #3**

DATE: 5/12/93

5 12 93



SITE: NL/Dutch Boy Paints Site
LOCATION: Perth Amboy, New Jersey
DESCRIPTION: OHM cleaning up PCB
debris in bldg #3
DATE: 5/12/93



SITE: NL/Dutch Boy Paints Site
LOCATION: Perth Amboy, New Jersey
DESCRIPTION: Spilled PCB oil and
debris in bldg #3
DATE: 5/12/93

5 12 93



SITE: NL/Dutch Boy Paints Site
LOCATION: Perth Amboy, New Jersey
DESCRIPTION: 3 cylinders found in
bldg #3
DATE: 5/12/93



SITE: NL/Dutch Boy Paints Site

LOCATION: Perth Amboy, New Jersey

**DESCRIPTION: Bag House Ports welded
closed to prevent migration**

DATE: 5/12/93



5 12 93

SITE: NL/Dutch Boy Paints Site
LOCATION: Perth Amboy, New Jersey
DESCRIPTION: Potential asbestos
insulation to be disposed, from bldg 4
DATE: 5/12/93



SITE: NL/Dutch Boy Paints Site
LOCATION: Perth Amboy, New Jersey
DESCRIPTION: Bldg #4 boiler room post
asbestos abatement
DATE: 5/12/93



SITE: NL/Dutch Boy Paints Site

LOCATION: Perth Amboy, New Jersey

**DESCRIPTION: OHM sampling drums in
bldg #4**

DATE: 5/12/93



SITE: NL/Dutch Boy Paints Site

LOCATION: Perth Amboy, New Jersey

**DESCRIPTION: Lab pack materials in
bldg #4**

DATE: 5/12/93



SITE: NL/Dutch Boy Paints Site
LOCATION: Perth Amboy, New Jersey
DESCRIPTION: Drums staged in bldg #4
DATE: 5/12/93



SITE: NL/Dutch Boy Paints Site

LOCATION: Perth Amboy, New Jersey

DESCRIPTION: Tanker truck pumping out
transformer oil from bldg 3 transformers

DATE: 5/14/93

5 14 93




SITE: NL/Dutch Boy Paints Site

LOCATION: Perth Amboy, New Jersey

**DESCRIPTION: OHM pumping out transformer
oil from bldg #3 transformers**

DATE: 5/14/93



SITE: NL/Dutch Boy Paints Site
LOCATION: Perth Amboy, New Jersey
DESCRIPTION: OHM pumping out transformer
oil from bldg #3 transformers
DATE: 5/14/93

TOYOTA

TOYOTA

5 14 93

SITE: NL/Dutch Boy Paints Site
LOCATION: Perth Amboy, New Jersey
DESCRIPTION: ERCS loading out drums
of lead contaminated soil and debris
DATE: 5/14/93

TESO 210

NYS DEC PA 206
NJ DEP 50002

STRICK

100 CU YDS.



45

WILSONS WHITE
MAYERS CHEM TO
ELIMINATE CO
402-758-1

1303
WARNING
13 G
HIGH TRAILER

ALL WAYS TO
IMPROVE TRAILERS
WILL BEAP 100
WITH 100% OF
STREET, WARE
HOUSE, TRAILER

5 14 93

SITE: NL/Dutch Boy Paints Site
LOCATION: Perth Amboy, New Jersey
DESCRIPTION: ERCS loading out drums
of lead contaminated soil and debris
DATE: 5/14/93



SITE: NL/Dutch Boy Paints Site
LOCATION: Perth Amboy, New Jersey
DESCRIPTION: OHM double-bagging misc
asbestos containing material
DATE: 5/14/93



5 17 93

SITE: NL/Dutch Boy Paints Site

LOCATION: Perth Amboy, New Jersey

**DESCRIPTION: OHM relocating transformers
in bldg #3 utilizing the existing crane**

DATE: 5/17/93



5 17 23

SITE: NL/Dutch Boy Paints Site

LOCATION: Perth Amboy, New Jersey

**DESCRIPTION: Area #3 post clean-up after
rain H2O floated casing matl to surface**

DATE: 5/17/93

T-13

52093

SITE: NL/Dutch Boy Paints Site

LOCATION: Perth Amboy, New Jersey

DESCRIPTION: T13 found in a panel box
in bldg #3 near T6-8

DATE: 5/20/93





T. 14

5 20 93

SITE: NL/Dutch Boy Paints Site

LOCATION: Perth Amboy, New Jersey

**DESCRIPTION: T14 found in a panel box
in bldg #3 near T6-8**

DATE: 5/20/93

52093

F8

SITE: NL/Dutch Boy Paints Site
LOCATION: Perth Amboy, New Jersey
DESCRIPTION: T7 and T8 restaged via
crane to the entrance of bldg #3
DATE: 5/20/93